



DEPARTMENT OF
WATER RESOURCES

CENTRAL SACRAMENTO AREA *Fact Sheet* Site 99.5

Emergency Levee Repairs Fall 2006

Location

River: Sacramento River

River Mile: 99.5

Longitude/Latitude:

N38.863780

W121.793630

Nearest Community:

Knights Landing

County: Yolo

Bank: Right

Length of Repair

1,000 feet (approximate)*

Repair Type

Rock material

Lead Agency

Department of Water Resources

* Length of repair may change.

**For further information,
please contact:**

Elizabeth Scott
DWR Public Affairs Office
(916) 835-5344
leveerepair@water.ca.gov

DEPARTMENT OF WATER RESOURCES
PO Box 942836, Sacramento, CA 94236

www.levees.water.ca.gov

